Lester Guard Station, Fire Warehouse (Warehouse, Bldg., No. 2232) Forest Service Road No. 45 Lester King County Washington

HABS WASH, 17-LEST, 1-C-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Western Region
Department of the Interior
San Francisco, California 94102

Form 10-920 (June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS WASH, 17-LEST, I-C-

HISTORIC AMERICAN BUILDINGS SURVEY ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR VICINITY	
Washington	King County		Lester	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)			HABS NO.	
Fire Warehouse (Source: C.J. Conover Report, July 30, 1942).			WA-172C	
SECONDARY OR COMMON NAMES OF STRUCTURE				
Warehouse (Bldg. #2232)		-		
COMPLETE ADDRESS (DESCRIBE LOCA	TION FOR RURAL SI	TES)		
Lot 15, Block D, near Forest Service Road #45, Section 23, Township 20N, Range 10E.				
C.1934 (Source: C.J. Conover July 30, 194	r Report, 42).	ARCHITECT(S) (INCL Unknown		
SIGNIFICANCE (ARCHITECTURAL AND The Fire Warehouse is part of transitional USDA Forest Serv with early Forest Service add	HISTORICAL, INCLU f the Lester Gua vice facility th	ard Station which at possesses st	ch is an increng histor	tact example of a rical associations
STYLE (IF APPROPRIATE) Vernacular	1 . 1			
MATERIAL OF CONSTRUCTION (INCLU- perimeter foundation. Droppe				
SHAPE AND OIMENSIONS OF STRUCTU Two story, rectangular (28' x				
EXTERIOR FEATURES OF NOTE The with exposed rafter ends and 10' x 10') constructed with be Windows are typical wooden,	kneebraces and eaded board (3/4	seven track-mou "x3-1/2" T&G)	nted slidi and X-brac	ing, rails and stiles
soil floors, one raised (+2'- floor, open and unpartitioned unfinished and wood frame str	-6") work bay, t d storage/sleepi ructure is expos	two work bays at ing area; second ed throughout.	concrete floor. A Simply co	ll interior space is nstructed (cont)
MAJOR ALTERATIONS AND ADDITIONS been made. Elaborate weather ridge.	SWITH DATES _{Nom} r station appara	major alteration atus is located	ns or addit on the nor	ions appear to have th end of the roof
PRESENT CONDITION AND USE Fair exterior stairs and siding sl certain. The Washington Sta	how deterioratio te Department of	on. The future Natural Resour	use of thi	s building is un- may use it (cont)
other information as appropriation similar to those on Gas and colding doors is also located Windows match those implace of	Oil House and Bu d on interiors o	nkhouse. Beade of Guard Station	ed board us Residence	ed to construct
SOURCES OF INFORMATION (INCLUDIA				RS, ETC.)
See continuation sheet.			·	
COMPILER, AFFILIATION				DATE
Katherun u Krafft Architectural Researcher			November 1985	

Katheryn H. Krafft, Architectural Researcher

ARCHITECTURAL DATA FORM CONTINUATION SHEET

HISTORIC NAME:

Fire Warehouse

COMMON NAME:

Warehouse (Bldg. #2232)

SIGNIFICANCE (continued)

development of Forest Service policy and the accomplishments of the Civilian Conservation Corps.

INTERIOR FEATURES OF NOTE (continued)

closets, storage bins and work benches are located on both floor levels. Flooring at raised bay and second floor is 2x6 (T&G) decking. The second floor area is distinguished by an extensive system of exposed wooden trusses.

PRESENT CONDITION AND USE (continued)

periodically for fire protection purposes in the future. This building is currently vacant and not in use.

SOURCES OF INFORMATION (continued)

Conover, C.J., "Lester CCC Camp, F-23", July 30, 1942. Unpublished manuscript on file at USDA Forest Service, Mount Baker-Snoqualmie National Forest, Seattle, WA.

Property records, Lease Agreements, general USFS correspondence. Unpublished documents in files of USDA Forest Service, Mount Baker-Snoqualmie National Forest, Seattle, WA.

Warehouse (blog#2232) Legter gvard station King county Legter, washington

